

## 2024.12.4 | Fix Bug

Fix: Sound not working properly when used on PS5.

Download

—

### How to Update?

Step 1: Download the driver update package above


Step 2: Plug the USB Dongle into the PC (the update process needs to be done on the PC)

Step 3: Click on the update package (if you encounter a file quarantine situation, please add the update package to the whitelist)




G06  
WirelessHeadse  
tFW Upgrade  
Tool V\_1.0.1

Step 4: Check if the USB Dongle is recognized.



Step 5: Click UpgradeFW

Step 6: Wait for the display of Successful



Step 7: Re-plug the USB Dongle

Step 8: Press and hold the headset power button for 5 seconds and wait for matching.